DATE 2318Z 30 JUN 65	ger (g.) top the state description and control of the the state of th	T Jacobs J.	
TO DIRECTOR 25X FROM ACTION:	1A	6 DFZ	PRIORITY
TOR: 2335Z 30 JUN 6	S5 INFO	05191-20 CITE	1N-95437 25)
IDEALIST (1A ATTENTION: [

- 1. CAMERA 119 WAS USED IN MISSION 0245C FLOWN ON 30 APRIL 1965.
 PROCESSING WAS ACCOMPLISHED IN THE FIELD.
 - 2. ORIGINAL NEGATIVE:
 - A. EXPOSURE WAS ADEGIATE AND THE RESOLUTION WAS GOOD. ;
- B. 9R SIDE: A PROCESSING DENSITY CHANGE IS APPARENT IN FRAME 612. THERE IS A HEAT SPLICE BETWEEN FRAMES 674/675. SCOTCH TAPE WAS USED FOR A SPLICE BETWEEN FRAMES 1281/1282.
- C. 9L SIDE: FRAMES 134 TO 137 ARE CRIMPED AND ARE ACCOMPANIED WITH PROCESSING MARKS. A PROCESSING DENSITY CHANGE IS PRESENT IN FRAME 773. THE SPLICES BETWEEN FRAMES 1099 TO 1100 AND 1185 TO 1186 APPEAR TO BE MADE WITH SCOTCH TAPE.
- D. BOTH SIDES: ROLLER CHATTER IS PRESENT ON THE INBOARD RP KB KB KB THROUGHOUT THE MISSION. IRREGULAR PLUS DENSITY MARKS AND WC DB THE STREAKS APPEAR INTERMITTENTLY IN THE MISSION. THE LAST TITLED FRANCE PA

Approved For Release 2003/03/28 CIA RDP66B00597R000400020005-5

Approved For Release 2003/03/28: CIA-RDP66B00597R000400020005-5

25X1A

PAGE 2

ON BOTH SIDES IS FRAME 1304.

- E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.
- 3. POSITIVE:
 - A. PI SUITABILITY WAS GOOD.
 - B. PRINTING AND PROCESSING WAS ADEQUATE.
 - C. THE APPROXIMATE CLOUD COVER IS 35 PERCENT.

END OF MESSAGE